

F01

03  
05  
07  
09  
11  
13  
15  
17  
19  
21  
23  
25

# 对刀器 Preset Gauge

F



加工中心伴侣、操作工的助手

带有磁性底座，放置稳定牢固  
外形美观、小巧实用，精度高  
调整简单方便



## 定中心杠杆指示表

CENTERING DIAL INDICATOR



803-101

F02
04
06
08
10
12
14
16
18
20
22
24
26

### 主要技术参数 SPECIFICATIONS

货号	型号	分度值	测量范围	直测头长度	弯测头长度	中心顶尖长度	夹持柄直径	量头直径
Nr.	Model	Grad.	Range	(mm)	(mm)	(mm)	(mm)	(mm)
803-101	WL36	0.01mm	0-3 mm	45,100,154	46,100,154	52.5	10	3
803-301	WL36	0.0005in	0.15in	45,100,154	46,100,154	52.5	9.52	3



Pursuing  
The Precision  
Serving  
The World

## 对刀器(Z轴设定器) PRESET GAUGES (Z axis setter)

01

F03

05

### 使用方法

- 将对零轴转至TEST
- 按下对刀平面至静止，转数指针会指示零位，转动表圈使大指针对零位
- 使用时将对零轴转至USE
- 将对刀器放在工件上，把磁性座的开关转到“ON”，刀具慢速进给至对刀面，使大、小指针同时对零位，则刀具与工件的距离是100mm

### FEATURES

- Turn the button of setting-zero from "use" to "test";
- Press down, the small indicator will show "0", keep your hand and then adjust indicator to be zero at long-needle;
- Turn the button of setting-zero to "use" before use;
- Put on the work piece, cutter touch probe side, when the long-needle and short-needle moving to "0" at the same time, the distance of the cutter with work piece is 100mm.

### 注意事项

1. 为更好的保证对刀器的精度，使用时避免放于未经加工的毛坯面
2. 请勿靠近温度超过100℃的热源，以防脱磁。



801-112


产品名称 对刀器

产品型号 DDQ50、DDQ100

高度 50mm、100mm

允许误差 0.01mm

外形尺寸图 DIMENSIONS(mm)



**对刀器 (Z轴设定器)**  
PRESET GAUGES (Z axis setter)

02

**F04**

06

08

10

12

14

16

18

20

22

24

26



801-101



801-311

**主要技术参数 SPECIFICATIONS**

货号 Nr.	型号 Model	高度 Height (mm)	分度值 Grad. (mm)	行程≥ Range(mm)	L (mm)	W (mm)	说明 Explanation
801-101	DDQ50	50	0.01	1.5	56	57	方形、表头内置、底面无磁性 Squre base,Inside indicator,Non-magnetic
801-111	DDQ50	50	0.01	1.5	56	57	方形、表头内置、底面有磁性 Squre base,Inside indicator,Magnetic
801-112	DDQ100	100	0.01	1.5	70	59	底面有磁性 (附开关) Magnetic(With switch)
801-201	DDQ50i	2"	0.001"	0.06"	2.20"	2.24"	方形、表头内置、底面无磁性 Squre base,Inside indicator,Non-magnetic
801-211	DDQ50i	2"	0.001"	0.06"	2.20"	2.24"	方形、表头内置、底面有磁性 Squre base,Inside indicator,Magnetic
801-301	DDQ50i	2"	0.0005"	0.06"	2.20"	2.24"	方形、表头内置、底面无磁性 Squre base,Inside indicator,Non-magnetic
801-311	DDQ50i	2"	0.0005"	0.06"	2.20"	2.24"	方形、表头内置、底面有磁性 Squre base,Inside indicator,Magnetic
801-212	DDQ100i	4"	0.001"	0.06"	2.76"	2.32"	底面有磁性 (附开关) Magnetic(With switch)
801-312	DDQ100i	4"	0.0005"	0.06"	2.76"	2.32"	底面有磁性 (附开关) Magnetic(With switch)